

CCP

INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

C-O-N-F-I-D-E-N-T-I-A-L

25X1

COUNTRY Hungary

REPORT

SUBJECT

Description of Hungarian Machines

DATE DISTR.

19 December 1956

NO. PAGES

1

25X1

REQUIREMENT
NO.

RD

DATE OF
INFO.

REFERENCES

25X1

PLACE &
DATE ACQ.

SOURCE EVALUATIONS ARE DEFINITIVE APPRAISAL OF CONTENT IS TENTATIVE

25X1

60

C-O-N-F-I-D-E-N-T-I-A-L

25X1

| | | | | | | | | | | | | | | | |
|--|---|------|---|------|---|-----|---|-----|--|-----|--|--|--|--|--|
| STATE | X | ARMY | X | NAVY | X | AIR | X | FBI | | AEC | | | | | |
| (Note: Washington distribution indicated by "X"; Field distribution by "#".) | | | | | | | | | | | | | | | |

INFORMATION REPORT INFORMATION REPORT

CONFIDENTIAL



25X1

MM

HUNGARY.



Economic.

Hungarian Machines



25X1

1. Wood-working machine
(Multiple direction
cutter?)




Table rather rough

2. Turbine.

Well made and finished.

3. One welding set
(generator)

Well finished.

25X1

4. Diesel Generator.

Poor looking.

5. Electrical Control
Panel.

Poor looking.

6/.....

CONFIDENTIAL



25X1

CONFIDENTIAL

25X1



-2-

6. Motors

7. Audio-Frequency
R.C. oscillator

All right in appearance.

8. Automatic saw

Poor.

9. Horizontal
Milling
Machine.

Good finish
Construction also
looked good.

25X1

10. Drill

Poorly finished.

11. Electric Motor

Finish poor.

12. Vertical Bench
Drill

CONFIDENTIAL

25X1



Sanitized Copy Approved for Release 2010/02/17 : CIA-RDP80T00246A031800600001-2

Page Denied

25X1

Sanitized Copy Approved for Release 2010/02/17 : CIA-RDP80T00246A031800600001-2